

大 连 星 镁 矿 业 有 限 公 司

STAR GRACE MINING CO., LTD.

Add: 29-67, No.929, Xinan Road, Shahekou District, Dalian, Liaoning, China

CERTIFICATE OF ANALYSIS

PRODUCT : FERRO BORON

WE HAVE INSPECTED THE QUALITY OF THE ABOVE MENTIONED GOODS AND FOUND THE RESULT OF INSPECTION AS FOLLOWS :

ITEMS	SPECIFICATIONS	RESULTS
B	15~20%	18.16%
C	1.0% max	0.23%
Si	4.0% max	0.26%
Al	6% max	0.23%
P	0.1% max	0.033%
S	0.01% max	0.006%
Size	10-60 mm	
CONCLUSION	CONFORM TO STANDARD	

STAR GRACE MINING CO., LTD.
大连星镁矿业有限公司

Wang Xiu Ling